



Duramax Replacement Wear Parts for your Diamond Z 7000

Tips/Teeth

- A Tip: 3"•x•5"•(7/8" Holes) Bottom Measurements
- AD Tip: 3"•x•5"•(7/8" Holes) Bottom Measurements
- ADT Tip: 3-3/8"•x•5-1/8"•(7/8" Holes) Bottom Measurements

Hardware- Bolts, Nuts, Washers

Bolts

- 7/8" GWP Heavy Duty 2•1/2" – 7•1/2"•Fine
- 7/8" GWP Heavy Duty 2•1/2" – 7•1/2"•Coarse
- 7/8"•Regular•Headed•2•1/2" – 7•1/2"•Fine
- 7/8"•Regular•Headed•2•1/2" – 7•1/2"•Coarse

Nuts

- 7/8"•Flange•Nut•Lock•Fine
- 7/8"•Flange•Nut•Lock•Coarse
- 7/8"•Flange•Nut•Fine
- 7/8"•Flange•Nut•Coarse
- 7/8"•Nut•Lock•Fine
- 7/8"•Nut•Lock•Coarse
- 7/8"•Non-Lock Nut Fine
- 7/8"•Non-Lock Nut Coarse

Screens/Grates

- 7000•Screen•1" Thick
- 7000 Screen 1- 1/4" Thick
- 7000 Screen 1- 1/2" Thick
- Material: T-1, AR-400
- Hole Patterns (In Any Size)
 - Round
 - Diamond
 - Square
 - Octagon
 - Hexagon
 - Rectangle

- Herringbone
- Slanted
- Custom
- Options: Rails, Baffles, Hardfacing, Backing, Bevels, Anvils

Hammers-Fixed and Swing

- 7000•Left•Hammer•3” Thick
- 7000•Right•Hammer•3” Thick

Rods

- 7000 Mill Rod
- 7000 Mill Rod Drilled and Tapped

Hammermills

Cutter bars

Wear plates

- 7000 Infeed Wear Plate•2” Thick
- 7000•Wear•Plates• $\frac{3}{4}$ ”•Thick
- 7000•Front•Mill•Cover• $\frac{3}{4}$ ”•Thick
- 7000•Rear•Mill•Cover• $\frac{3}{4}$ ”•Thick

Infeed Chain

- 7000 Complete Floor Chain

Conveyor Belts

- 7000 Phase 1 Belt
- 7000 Phase 2 Belt

Conveyor Drive and Idler Rollers